

SYDNEY

25 – 27 Green St
East Botany, NSW 2019
Ph: +61 2 9666 3788
Fax: +61 2 9666 4805

MELBOURNE

29 Trade Place
Vermont, VIC 3133
Ph: 03 9872 4033
Fax: 03 9872 4099

BRISBANE

Unit 6/5 Deakin Street
Brendale, QLD 4500
Ph: 07 3205 8510
Fax: 07 3205 9616

SINGAPORE

H.K. Moey
9 Elias Terrace
Singapore 519772
Ph: +65 6582 8103
Fax: +65 6584 8100
Mobile: +65 9751 0026



TECHNICAL DATA
Erabond 6100 Primer
Polyurethane Primer

DESCRIPTION

Erabond 6100 primer is a high solids, 2 component urethane primer with outstanding adhesion to properly prepared steel, ductile iron and galvanised substrates. It is specially formulated to provide excellent anti corrosive properties and accept fast-set and standard-set polyurethanes.

FEATURES

- Convenient 1:1 mix ratio
- Excellent adhesion to aged Polyurethane and Polyurea coatings
- Very good chemical resistance
- High flexibility and impact resistance
- Prevents undercutting

PHYSICAL CHARACTERISITICS

Mix Ratio (Volume)	1:1
Potlife @15°C	1.5-2 hrs
Potlife @24°C	1-1.5 hrs
Potlife @32°C	0.5-1 hrs
Solids Content by Volume	55%
Solids Content by Weight	68%
Theoretical Coverage	2.1m ² @ 1mm
Recommended DFT	1-3 mil
Number of Coats	1

SURFACE PREPARATION

It is essential to remove all oil, grease, cutting / drilling compounds, and other surface contaminants prior to further preparation of the metal surface. This is achieved using a biodegradable degreasing solution in accordance with AS1627.1. Alternatively solvent wiping using a solvent-based degreaser can be used. Clean dry untreated rags must be used and changed regularly to ensure the oil is removed and not spread over a larger area.

This information is of general nature and is supplied without recommendation of guarantee. It does not make claim to be free from patent infringement. Properties shown are typical and do not imply specification tolerances. Era Polymers cannot accept liability for loss or damage through use. Whilst these technical details are based on expert knowledge, practical experience and laboratory testing, successful application depends upon the nature and conditions in which the products are supplied. Users must, by comprehensive testing, evaluate this product in their own application.



Era Polymers Pty. Ltd.

A.B.N. 14 003 055 936

erapol@erapol.com.au
www.erapol.com.au

SYDNEY

25 – 27 Green St
East Botany, NSW 2019
Ph: +61 2 9666 3788
Fax: +61 2 9666 4805

MELBOURNE

29 Trade Place
Vermont, VIC 3133
Ph: 03 9872 4033
Fax: 03 9872 4099

BRISBANE

Unit 6/5 Deakin Street
Brendale, QLD 4500
Ph: 07 3205 8510
Fax: 07 3205 9616

SINGAPORE

H.K. Moey
9 Elias Terrace
Singapore 519772
Ph: +65 6582 8103
Fax: +65 6584 8100
Mobile: +65 9751 0026

Soluble salts and biodegradable degreasing solution residue shall be removed by low pressure water washing (approx. 20 MPa) using potable water.

Grind all sharp edges and corners to a minimum radius of 2mm. Remove all weld slag and spatter, and grind all weld seams and high spots smooth.

Mild Steel

Abrasive blast all surfaces in accordance with AS1627.4 to a minimum Sa2½ (AS1627.9). A surface profile of 50 – 75 µm shall be achieved. Dust / vacuum down to remove all preparation residues. Blasted surfaces shall be primed prior to surface deterioration or contamination. The surface shall resemble the specified visual standard and profile immediately prior to priming.

Aluminium, Galvanized Steel, Stainless Steel

Low pressure sweep abrasive blast using inert media (e.g. garnet) to achieve a roughened uniform flat appearance over the entire surface. Dust / vacuum down to remove all preparation residues. Blasted surfaces shall be primed with four hours, and before surface contamination occurs.

Other Metals

Test patches of the complete coating system should be examined and tested for adhesion to ensure suitability of Erabond 6100 Primer for other metallic surfaces.

PRODUCT MIXING

The mix ratio of Erabond 6100 Primer is 1:1 by volume. Each component needs to be mechanically mixed before adding together. They should be combined at a 1:1 ratio and mechanically mixed to a smooth consistency.

ADDITION OF THINNERS

Addition of thinners to Erabond 6100 Primer is not normally required

APPLICATION

Erabond 6100 Primer is best applied by siphon or pressure pot spray equipment. Airless spray equipment may be used, provided a maximum of 12.5µm DFT is applied.

Erabond 6100 Primer is applied in a single wet pass with 50% overlap. Hold the gun at right angles to the surface approx. 20-30 cm away. Make even, parallel passes and spray approx. 80µm Wet Film Thickness (WFT) to achieve 9µm DFT. A thicker film is not required. The desired film thickness will be obtained when the film appearance is continuous, but mottled and translucent.

CLEAN UP

Clean all mixing and application equipment immediately after use with MEK.

This information is of general nature and is supplied without recommendation of guarantee. It does not make claim to be free from patent infringement. Properties shown are typical and do not imply specification tolerances. Era Polymers cannot accept liability for loss or damage through use. Whilst these technical details are based on expert knowledge, practical experience and laboratory testing, successful application depends upon the nature and conditions in which the products are supplied. Users must, by comprehensive testing, evaluate this product in their own application.

Version: 1

Date of Issue: 9/9/2008

Page 2 of 2
Erabond 6100 Primer

